Attorney Docket No. 9180-5

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

h re: Mis et al.

OCT 0 1 2004

U.S. Patent No.: 6,762,122 B 2_

Application Serial No.: 09/966,316

Issued: July 13, 2004

Filed: September 27, 2001

Methods of Forming Metallurgy Structures for Wire and Solder Bonding For:

Date: September 29, 2004

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Certificate OCT 0 62004

of Correction

REQUEST FOR ENTRY OF CERTIFICATE OF CORRECTION UNDER 35 U.S.C §254 AND 37 C.F.R. §1.322

Sir:

The Assignee of record for the above-referenced patent hereby requests, pursuant to 35 U.S.C §254 and 37 C.F.R. §1.322, that a Certificate of Correction be issued. This request is made in order to correct the mistakes incurred through the fault of the U.S. Patent and Trademark Office. No fee is believed due. However, the Commissioner is authorized to charge any deficiency or credit any overpayment to Deposit Account No. 50-0220.

The mistakes appearing in the patent are set forth with corrections on the Certificate of Correction enclosed herewith, with an additional copy thereof and a return post card.

Respectfully submitted,

Registration No. 38

Myers Bigel Sibley & Sajovec, P.A.

P. O. Box 37428

Raleigh, North Carolina 27627

Telephone: (919) 854-1400 Facsimile: (919) 854-1401

Customer No. 20792

Certificate of Mailing under 37 CFR 1.8

I hereby certify that this correspondence is being deposited with the United States Postal Service with sufficient postage as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on September

OCT 0 8 2004

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,762,122 82

DATED

July 13, 2004

INVENTOR(S)

Mis et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Claims:

Column 11, line 15 should read -- first barrier layer comprising nickel on the first under --

Column 11, line 24 should read -- and a gold layer on the second barrier layer comprising --

Column 12, line 31 should read -- input/output pad, and a gold layer on the second barrier --

MAILING ADDRESS OF SENDER: Myers, Bigel, Sibley & Sajovec P.O. Box 37428 Raleigh, NC 27627 PATENT NO. 6,762,122 632—No. of additional copies:

_

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you are required to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.



Attorney Docket No. 9180-5

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re: Mis et al.

U.S. Patent No.: 6,762,122 62

Application Serial No.: 09/966,316

Issued: July 13, 2004

Filed: September 27, 2001

: Methods of Forming Metallurgy Structures for Wire and Solder Bonding

Date: September 29, 2004

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR ENTRY OF CERTIFICATE OF CORRECTION UNDER 35 U.S.C §254 AND 37 C.F.R. §1.322

Sir:

The Assignee of record for the above-referenced patent hereby requests, pursuant to 35 U.S.C §254 and 37 C.F.R. §1.322, that a Certificate of Correction be issued. This request is made in order to correct the mistakes incurred through the fault of the U.S. Patent and Trademark Office. No fee is believed due. However, the Commissioner is authorized to charge any deficiency or credit any overpayment to Deposit Account No. 50-0220.

The mistakes appearing in the patent are set forth with corrections on the Certificate of Correction enclosed herewith, with an additional copy thereof and a return post card.

Respectfully submitted,

Scott C. Hatfield

Registration No. 38,1

Myers Bigel Sibley & Sajovec, P.A.

P. O. Box 37428

Raleigh, North Carolina 27627 Telephone: (919) 854-1400

Facsimile: (919) 854-1401

Customer No. 20792

Certificate of Mailing under 37 CFR 1.8

I hereby certify that this correspondence is being deposited with the United States Postal Service with sufficient postage as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on September 20 2004

Monica L. Croom

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,762,122 B2

DATED

July 13, 2004

INVENTOR(S)

Mis et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Claims:

Column 11, line 15 should read -- first barrier layer comprising nickel on the first under --

Column 11, line 24 should read -- and a gold layer on the second barrier layer comprising --

Column 12, line 31 should read -- input/output pad, and a gold layer on the second barrier --

MAILING ADDRESS OF SENDER: Myers, Bigel, Sibley & Sajovec P.O. Box 37428 Raleigh, NC 27627 PATENT NO. 6,762,122 B2-No. of additional copies:

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you are required to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.